





×



×

Bottomview

Axonometry



×

Elevation AA

Elevation BB

×

element name:	ventilation duct	condition assessment:	good, normal signs of use
function:	distribution of fresh air in building	material:	galvanized steel with grooves
dimensions (length x width x height):	1500mm x 700mm x 300mm	material thickness:	0,7 mm
weight per element (kg):	18,3 kg	raw material density (kg/m3):	7850 kg/m3
actual location:	in the ceiling	embodied energy:	2434 MJ/m³
count:	2400 m	risk of contamination:	no
accessibility:	easy	exposition:	indoor, not exposed to weathering
deconstruction tool:	screwdriver	treatment / finishing:	galvanized
fabricator:	Trox Hesco	color:	silver
made in:	Denmark	drawing scale:	1:25